

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Problem Image Mailbox.**




FIGURE 1




Fig. 2




FIGURE 3




Fig. 4





FIG 5






Fig.6




Fig. 7







Fig. 8

Envelop  
LOA 765  
LBP 700  
Sponson Tangent @ sta 4 1/5











Fig. 10
















Fig. 16




Fig. 17




Fig. 18

Envelop  
LOA 763  
LBP 700




FIGURE 19




Fig. 20




FIG. 21